

# General Environmental Incident Summary

**Incident:** 3438      **Date/Time Notice:** 8/25/2014      **DEM Incident No:**  
**Responsible Party:** Key Energy Services  
**Date Incident:** 8/18/2014      **Time Incident:** 07:45      **Duration:** 5 minutes  
**County:** McKenzie      **Twp:** 151      **Rng:** 96      **Sec:** 10      **Qtr:** NW NE  
**Lat:** 47.91259      **Long:** -102.94230      **Method:** Interpolation from map  
**Location Description:** From State Hwy 23 and 35th street travel south 4/10 of a mile west 600 ft. to site

**Submitted By:** Jerry Sparling      **Affiliation:** Supervisor  
**Address:** 6389 104th ave.  
**City:** Tioga      **State:** ND      **Zip:** 58852

## Received By:

**Contact Person:** Jerry Sparling  
6389 104 th ave.  
Tioga , ND 58852

**Distance Nearest Occupied Building:** 600 Feet      **Release Contained:** Yes

**Type of Incident:** Tank Overflow

**Description of Released Contaminant:** Salt Water

**Volume Spilled:** 3.00 barrels

**Ag Related:** No

**EPA Extremely Hazardous Substance:** No

**Reported to NRC:** Unknown

## Cause of Incident:

Electric Valve Malfunctioned and caused overflow

## Risk Evaluation:

None

**# of Fatalities:**      **# of Injuries:**      **Affected Medium:** 03 - soil

## Potential Environmental Impacts:

None

## Action Taken or Planned:

Fluid was contained in berm area cleaned up and put back into system  
soil was recovered and will be hauled to a certified land recovery facility

**Wastes Disposal Location:** Indian Hills Disposals Land Facility

## Agencies Involved:

## ***Updates***

---

***Date:*** 8/25/2014

***Status:*** Reviewed; O&G Lead

***Author:*** Roberts, Kris

***Updated Volume:***

***Notes:***

Release of 3 bbls of salt water brine, due to a valve malfunction, appears to have remained on an oil production facility or a saltwater disposal facility. NDIC retains oversight. Report forwarded to NDIC.